

Protective clothing



Protection

Wear safety glasses to protect the eyes against hazardous substances. Do not wear regular eyeglasses or sunglasses.



Body Protection

Wear long pants or equivalent at all times in the laboratory.
Wear laboratory coats when hazardous chemicals, biological or unsealed radiological materials are used. Flame resistant lab coats must be worn when working with pyrophoric materials or large quantities of flammable liquids.



Wear gloves to protect the hands against hazardous chemicals, biological or unsealed radiological materials. Do not wear mittens, gloves without fingers, or sports gloves.



Foot Protection

Wear closed toe shoes. Do not wear sandals, slippers or flip-flops, shoes with open toes, or shoes not enclosing the entire foot.